



**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
LARGE AIRCRAFT**

BIWEEKLY 2000-01

This electronic copy may be printed and used in lieu of the FAA biweekly paper or microfiche copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Airworthiness Programs Branch, AFS-610
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-4104

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Biweekly 2000-01			
99-27-01		Pratt & Whitney	Engine: JT8D-209, -217, -217A, -217C, and -219
99-27-03		Fokker	F27 Mark 050 Series
99-27-04		Rolls-Royce	Engine: Dart 506, 510, 511, 514, 525, 526, 529, 530, +
99-27-05		Boeing	767-200, -300, and -300F Series
99-27-06		Boeing	757-200, -200PF, and -200CB Series
99-27-07	S 98-25-53	Airbus	A300 B4-600R and A300 F4-600R Series
99-27-08		SAAB	SAAB SF340A and SAAB 340B Series
99-27-09		Airbus	A300 B4-203 Series
99-27-10		Airbus	A310 and A300-600 Series
99-27-11		British Aerospace	BAC 1-11 200 and 400 Series
99-27-13		Fokker	F27 Mark 050 Series
99-27-14	S 99-01-05	Airbus	A340-211, -212-, -213, -311, -312, and -313 Series
99-27-15		General Electric	Engine: GE90-76B, -77B, -85B, -90B, and -92B
99-27-16		CFE	Engine: CFE738-1-1B
2000-01-51	E	Bombardier	CL-600-2B16 (CL-604)

**PRATT & WHITNEY
AIRWORTHINESS DIRECTIVE
ENGINE
LARGE AIRCRAFT**

99-27-01 Pratt & Whitney: Amendment 39-11482. Docket 98-ANE-80-AD. Issued December 20, 1999.

Applicability: Pratt & Whitney (PW) JT8D-209, -217, -217A, -217C, and -219 series turbofan engines, installed on, but not limited to, McDonnell Douglas MD-80 series airplanes.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent an uncontained blade failure that could result in damage to the airplane, accomplish the following:

Inspection

(a) For JT8D-209, -217, and -217A engines, perform the 3rd and 4th stage low pressure turbine (LPT) blade torque inspections in accordance with the intervals and procedures described in PW Service Bulletin (SB) No. 6224, Revision 2, dated August 27, 1998, Accomplishment Instructions, Part 1, A(1) through B(3).

(b) For JT8D-217C and -219 engines, perform the 4th stage LPT blade torque inspection in accordance with the intervals and procedures described in PW SB No. 6224, Revision 2, dated August 27, 1998, Accomplishment Instructions, Part 2, C(1) through C(3).

Effective Date for Computing Compliance Intervals

(c) For the purpose of this AD, use the effective date of this AD for computing compliance intervals whenever PW SB No. 6224, Revision 2, dated August 27, 1998, refers to the publication date of the SB.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

Ferry Flights

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) The actions required by this AD shall be done in accordance with PW SB No. 6224, Revision 2, dated August 27, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Pratt & Whitney, 400 Main St., East Hartford, CT 06108; telephone (860) 565-8770, fax (860) 565-4503. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(g) This amendment becomes effective on February 2, 2000.

FOR FURTHER INFORMATION CONTACT: Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7175, fax (781) 238-7199.

**FOKKER
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-03 FOKKER: Amendment 39-11484. Docket 99-NM-235-AD. Issued December 21, 1999.

Applicability: Model F27 Mark 050 series airplanes, serial numbers 20103 through 20298 inclusive; certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking in the skin and stringers, which could result in reduced structural integrity of the wings, accomplish the following:

(a) Perform a detailed visual inspection of the connections between ribs 11260, 11860, 12660, and 13460, and stringers 4, 5, 6, and 7 of the top and bottom wing skins to detect loose or missing rivets or gaps, in accordance with Part 1 of Fokker Service Bulletin SBF50-57-019, dated February 27, 1998; at the time specified in paragraph (a)(1), (a)(2), (a)(3), or (a)(4) of this AD, as applicable. Repeat the inspection thereafter at intervals not to exceed 2,500 flight cycles.

(1) For airplanes that have accumulated less than 15,000 total flight cycles as of the effective date of this AD: Inspect prior to the accumulation of 15,000 total flight cycles, or within 12 months after the effective date of this AD, whichever occurs later.

(2) For airplanes that have accumulated 15,000 total flight cycles or more but less than 20,000 total flight cycles as of the effective date of this AD: Inspect within 12 months after the effective date of this AD.

(3) For airplanes that have accumulated 20,000 total flight cycles or more but less than 25,000 total flight cycles as of the effective date of this AD: Inspect within 6 months after the effective date of this AD.

(4) For airplanes that have accumulated 25,000 total flight cycles or more as of the effective date of this AD: Inspect within 3 months after the effective date of this AD.

NOTE 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc. may be used. Surface cleaning and elaborate access procedures may be required."

(b) Except as provided by paragraph (d) of this AD, if no loose or missing fastener, or no gap is found during any inspection required by paragraph (a) of this AD, prior to the accumulation of 40,000 total flight cycles, or within 18 months after the effective date of this AD, whichever occurs later, modify the rib-stringer connections (i.e., reaming of rivet holes, rotating probe eddy current inspections, corrective actions, and installation of connecting angles) in accordance with Part 2 of the Accomplishment Instructions of Fokker Service Bulletin SBF50-57-019, dated February 27, 1998. Accomplishment of the actions required by this paragraph constitutes terminating action for the repetitive inspection requirements of paragraph (a) of this AD.

(c) If any loose or missing fastener, or any gap is found during any inspection required by paragraph (a) of this AD, prior to further flight, accomplish the actions specified in paragraph (c)(1), (c)(2), or (c)(3) of this AD in accordance with Fokker Service Bulletin SBF50-57-019, dated February 27, 1998.

(1) Accomplish the modification specified in paragraph (b) of this AD.

(2) Except as provided by paragraph (d) of this AD, accomplish the temporary repair (i.e., surface probe eddy current inspection, repair, and installation of a shim and new blind rivets) in accordance with Part 3 of the Accomplishment Instructions of the service bulletin. Within 500 flight cycles after accomplishment of this temporary repair, accomplish the modification specified in paragraph (b) of this AD.

(3) Except as provided by paragraph (d) of this AD, accomplish the temporary repair (i.e., surface probe eddy current inspection, repair, and installation of connecting angles) in accordance with Part 4 of the Accomplishment Instructions of the service bulletin. Within 2,500 flight cycles after accomplishment of this temporary repair, accomplish the modification specified in paragraph (b) of this AD.

(d) If any discrepancy is found during any inspection required by paragraph (a), (b), or (c) of this AD; and Fokker Service Bulletin SBF50-57-019, dated February 27, 1998, specifies to contact Fokker for appropriate action: Prior to further flight, repair in accordance with either a method approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or the Rijksluchtvaartdienst (RLD) (or its delegated agent). For a repair method to be approved by the Manager, International Branch, ANM-116, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

NOTE 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(g) Except as provided by paragraph (d) of this AD, the actions shall be done in accordance with Fokker Service Bulletin SBF50-57-019, dated February 27, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, The Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

NOTE 4: The subject of this AD is addressed in Dutch airworthiness directive 1998-023/2, dated October 30, 1998.

(h) This amendment becomes effective on January 13, 2000.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**ROLLS-ROYCE LIMITED
AIRWORTHINESS DIRECTIVE
ENGINE
LARGE AIRCRAFT**

99-27-04 Rolls-Royce Limited: Amendment 39-11485. Docket 99-NE-30-AD. Issued December 21, 1999.

Applicability: Rolls-Royce Limited (R-R) Dart 506, 510, 511, 514, 525, 526, 529, 530, 531, 532, 535, 542, and 552 series turboprop engines, installed on but not limited to Gulfstream Aerospace Corp. G-159, British Aerospace HS 748, Fokker Aircraft F.27, Mitsubishi Heavy Industries YS-11, General Dynamics (Convair) 640 and 600 series, and Vickers Armstrongs (Aircraft Limited) Viscount.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of a propeller to auto-feather following an engine power loss, resulting in possible loss of control of the airplane due to high asymmetric drag, accomplish the following:

Inspection

(a) Within 3 months after the effective date of this AD, accomplish the following in accordance with the Action section of R-R Service Bulletin (SB) No. Da61-13, dated December 1996:

(1) Remove the switch cover, visually inspect the interior of the switch and replace the switch cover, all in accordance with the accomplishment instructions of the SB.

(2) If a Klixon low torque switch, part number (P/N) 6PS-25-1, is installed, prior to further flight remove the Klixon low torque switch from service and replace with an approved low torque switch.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Ferry Flights

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The actions required by this AD shall be done in accordance with R-R SB No. Da61-13, dated December 1996. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Rolls-Royce Limited, Attn: Dart Engine Service Manager, East Kilbride, Glasgow G74 4PY, Scotland; telephone: +44 1355-220-200, fax: +44 1141-778-432. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(e) This amendment becomes effective on February 28, 2000.

FOR FURTHER INFORMATION CONTACT: James Lawrence, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7176, fax (781) 238-7199.

**THE BOEING COMPANY
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-05 BOEING: Amendment 39-11486. Docket 97-NM-241-AD. Issued December 22, 1999.

Applicability: Model 767-200, -300, and -300F series airplanes, line numbers 1 through 607 inclusive; equipped with part number S160T300-series carbon brakes; certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the brake housing in the torque rod region, which could reduce the braking capability of the airplane and/or prevent the extension of a main landing gear, accomplish the following:

Replacement

(a) Within 360 days after the effective date of this AD, replace the hydraulic reducer fitting in the return port of the alternate brake selector valve with a new restrictor fitting, in accordance with Boeing Service Bulletin 767-32-0152, dated June 6, 1996; Revision 1, dated June 27, 1996; or Revision 2, dated July 10, 1997.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The replacement shall be done in accordance with Boeing Service Bulletin 767-32-0152, dated June 6, 1996; Boeing Service Bulletin 767-32-0152, Revision 1, dated June 27, 1996; or Boeing Service Bulletin 767-32-0152, Revision 2, dated July 10, 1997. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on February 8, 2000.

FOR FURTHER INFORMATION CONTACT:

David Herron, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2672; fax (425) 227-1181.

**THE BOEING COMPANY
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-06 BOEING: Amendment 39-11487. Docket 98-NM-323-AD. Issued December 22, 1999.

Applicability: Model 757-200, -200PF, and -200CB series airplanes powered by Rolls-Royce RB211-535C/E4/E4B turbofan engines, certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent engine thrust control cable failure, which could result in a severe asymmetric thrust condition during landing, and consequent reduced controllability of the airplane, accomplish the following:

Inspections and Corrective Actions

(a) Within 24 months or 6,000 flight hours after the effective date of this AD, whichever occurs first: Accomplish the "Thrust Control Cable Inspection Procedure" specified in Appendix 1. (including Figure 1) of this AD to verify the integrity of the thrust control cables. Prior to further flight, repair any discrepancy found in accordance with the procedures described in the Boeing 757 Maintenance Manual. Repeat the inspection thereafter at intervals not to exceed 24 months or 6,000 flight hours, whichever occurs first.

(b) For airplanes having line numbers 1 through 636 inclusive: Within 24 months or 6,000 flight hours after the effective date of this AD, whichever occurs first, perform a one-time inspection of the 8 engine thrust control cable pulleys in the struts (4 in each strut) to determine the part number (P/N) of each pulley. If any pulley having P/N 65B80977-1 or BAC30M4 is installed, prior to further flight, replace it with a pulley having P/N 255T1232-7, in accordance with the procedures described in the Boeing 757 Airplane Maintenance Manual.

NOTE 2 The location of the pulleys to be inspected in accordance with paragraph (b) of this AD is specified in Chapters 53-11-53-04, 76-11-52-01, and 76-11-52-02 of the Boeing 757 Illustrated Parts Catalog.

Modifications

(c) For airplanes identified in Boeing Service Bulletin 757-76-1, dated May 18, 1984: Within 24 months or 6,000 flight hours after the effective date of this AD, whichever occurs first, remove the guide bracket of the engine thrust control cable located on the front spar of the right wing in accordance with the service bulletin.

(d) For airplanes identified in Boeing Service Bulletin 757-76-0005, dated May 5, 1988: Within 24 months or 6,000 flight hours after the effective date of this AD, whichever occurs first, remove the engine thrust control cable breakaway stop assemblies, and replace sections of the engine thrust control cables with smaller diameter cables in accordance with the service bulletin.

(e) For airplanes identified in Boeing Service Bulletin 757-30A0018, Revision 2, dated September 9, 1999: Within 60 days after the effective date of this AD, install a support bracket assembly between the window heat wire bundle and the engine thrust control cable; and adjust the wire bundle clearance, as necessary, to parallel the minimum clearance specified in Boeing Alert Service Bulletin 757-30A0018, Revision 1, dated September 17, 1998; or Boeing Service Bulletin 757-30A0018, Revision 2, dated September 9, 1999.

Alternative Method of Compliance

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

NOTE 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(h) Except as provided by paragraphs (a) and (b) of this AD, the modifications shall be done in accordance with Boeing Service Bulletin 757-76-1, dated May 18, 1984; Boeing Service Bulletin 757-76-0005, dated May 5, 1988; Boeing Alert Service Bulletin 757-30A0018, Revision 1, dated September 17, 1998; and Boeing Service Bulletin 757-30A0018, Revision 2, dated September 9, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(i) This amendment becomes effective on February 7, 2000.

FOR FURTHER INFORMATION CONTACT:

Kathrine Rask, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1547; fax(425) 227-1181.

APPENDIX 1.

THRUST CONTROL CABLE INSPECTION PROCEDURE

1. General

A. Clean the cables, if necessary, for the inspection, in accordance with Boeing 757 Maintenance Manual 12-21-31.

B. Use these procedures to verify the integrity of the thrust control cable system. The procedures must be performed along the entire cable run for each engine. To ensure verification of the portions of the cables which are in contact with pulleys and quadrants, the thrust control must be moved by operation of the thrust and/or the reverse thrust levers to expose those portions of the cables.

C. The first task is an inspection of the control cable wire rope. The second task is an inspection of the control cable fittings. The third task is an inspection of the pulleys.

NOTE: These three tasks may be performed concurrently at one location of the cable system on the airplane, if desired, for convenience.

2. Inspection of the Control Cable Wire Rope

A. Perform a detailed visual inspection to ensure that the cable does not contact parts other than pulleys, quadrants, cable seals, or grommets installed to control the cable routing. Look for evidence of contact with other parts. Correct the condition if evidence of contact is found.

NOTE: For the purposes of this procedure, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

B. Perform a detailed visual inspection of the cable runs to detect incorrect routing, kinks in the wire rope, or other damage. Replace the cable assembly if:

(1) One cable strand had worn wires where one wire cross section is decreased by more than 40 percent (see Figure 1),

(2) A kink is found, or

(3) Corrosion is found.

C. Perform a detailed visual inspection of the cable: To check for broken wires, rub a cloth along the length of the cable. The cloth catches on broken wires.

(1) Replace the 7x7 cable assembly if there are two or more broken wires in 12 continuous inches of cable or there are three or more broken wires anywhere in the total cable assembly.

(2) Replace the 7x19 cable assembly if there are four or more broken wires in 12 continuous inches of cable or there are six or more broken wires anywhere in the total cable assembly.

3. Inspection of the Control Cable Fittings

A. Perform a detailed visual inspection to ensure that the means of locking the joints are intact (wire locking, cotter pins, turnbuckle clips, etc.). Install any missing parts.

B. Perform a detailed visual inspection of the swaged portions of swaged end fittings to detect surface cracks or corrosion. Replace the cable assembly if cracks or corrosion are found.

C. Perform a detailed visual inspection of the unswaged portion of the end fitting. Replace the cable assembly if a crack is visible, if corrosion is present, or if the end fitting is bent more than 2 degrees.

D. Perform a detailed visual inspection of the turnbuckle. Replace the turnbuckle if a crack is visible or if corrosion is present.

4. Inspection of Pulleys

A. Perform a detailed visual inspection to ensure that pulleys are free to rotate. Replace pulleys which are not free to rotate.




FIGURE 1

**AIRBUS INDUSTRIE
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-07 AIRBUS INDUSTRIE: Amendment 39-11488. Docket 99-NM-130-AD. Supersedes AD 98-25-53, Amendment 39-10956. Issued December 23, 1999.

Applicability: Model A300 B4-600R and A300 F4-600R series airplanes, on which Airbus Modification 4801 (trim tank system) has been accomplished, certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect damage to the fuel pump and fuel pump canister, which could result in loss of flame trap capability and could provide a fuel ignition source in the center fuel tank, accomplish the following:

Inspections

(a) Prior to the accumulation of 5,000 total hours time-in-service, or within 250 hours time-in-service after the effective date of this AD, whichever occurs later, perform a detailed visual inspection for damage of the center tank fuel pumps and fuel pump canisters, in accordance with Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998. Repeat the inspection prior to the accumulation of 12,000 total hours time-in-service, or within 250 hours time-in-service after accomplishment of the initial inspection, whichever occurs later. Thereafter, repeat the inspection at intervals not to exceed 250 hours time-in-service, until accomplishment of the initial inspection required by paragraph (b) of this AD.

NOTE 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(b) At the applicable time specified in paragraph (b)(1), (b)(2), or (b)(3) of this AD: Perform a detailed visual inspection to detect damage of the center tank fuel pumps and perform an eddy current inspection to detect damage of the fuel pump canisters, in accordance with Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999. Repeat the inspections thereafter at intervals not to exceed 1,500 flight cycles. Accomplishment of the initial inspections required by this paragraph constitutes terminating action for the requirements of paragraph (a) of this AD.

(1) For airplanes that have accumulated 11,000 or more total flight cycles as of the effective date of this AD: Inspect within 300 flight cycles after the effective date of this AD.

(2) For airplanes that have accumulated 8,500 or more total flight cycles, but fewer than 11,000 total flight cycles, as of the effective date of this AD: Inspect within 750 flight cycles after the effective date of this AD.

(3) For airplanes that have accumulated fewer than 8,500 total flight cycles as of the effective date of this AD: Inspect prior to the accumulation of 7,000 flight cycles, or within 1,500 flight cycles after the effective date of this AD, whichever occurs later.

(c) If any damage is detected during any inspection required by this AD, prior to further flight, replace the damaged fuel pump or fuel pump canister with a new or serviceable part in accordance with Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

NOTE 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) The actions shall be done in accordance with Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998; and Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999.

(1) The incorporation by reference of Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998, was approved previously by the Director of the Federal Register as of December 28, 1998 (63 FR 70639, December 22, 1998).

(3) Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

NOTE 4: The subject of this AD is addressed in French airworthiness directive 1999-149-280(B), dated April 7, 1999.

(g) This amendment becomes effective on February 8, 2000.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**SAAB AIRCRAFT AB
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-08 SAAB AIRCRAFT AB: Amendment 39-11489. Docket 99-NM-200-AD. December 23, 1999.

Applicability: Model SAAB SF340A series airplanes, serial numbers 004 through 159 inclusive; and Model SAAB 340B series airplanes, series number 160 through 459 inclusive; certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the power levers from binding due to the backing out of screws that secure the solenoid bracket within the flight idle stop assembly, which could result in the malfunction of the flight idle stop mechanism and the override function, and the inability to move the power levers aft of flight idle, accomplish the following:

Inspection

(a) Within 800 flight hours after the effective date of this AD, perform a borescopic inspection of the control quadrant for loose screws, in accordance with Saab Service Bulletin 340-76-043, Revision 01, dated July 29, 1999. If no loose screws are found, repeat the inspection thereafter at intervals not to exceed 800 flight hours, until the requirements of paragraph (c) are accomplished.

NOTE 2: Saab Service Bulletin 340-76-043, dated July 2, 1999, references Adams Rite Aerospace Service Letter General SL-01, dated April 6, 1999, as an additional source of service information to accomplish the inspection.

NOTE 3: Inspections and replacements accomplished prior to the effective date of this AD in accordance with Saab Service Bulletin 340-76-043, dated July 2, 1999, are considered acceptable for compliance with the applicable action specified in this amendment.

Corrective Action

(b) If any loose screw is found during any inspection performed in accordance with paragraph (a) of this AD, prior to further flight, replace the existing control quadrant with a modified control quadrant, or with a serviceable control quadrant that has been inspected and found to have no loose screws, in accordance with Saab Service Bulletin 340-76-043, Revision 01, dated July 29, 1999.

Terminating Action

(c) Within 8,000 flight hours or 6 years after the effective date of this AD, whichever occurs earlier: Replace the existing control quadrant with a modified control quadrant in accordance with Saab Service Bulletin 340-76-043, Revision 01, dated July 29, 1999. Such replacement constitutes terminating action for the repetitive inspections required by paragraph (a) of this AD.

Spares

(d) As of the effective date of this AD, no person shall install a control quadrant on any airplane, unless the quadrant has been modified, or has been inspected and found to have no loose screws, in accordance with the requirements of this AD.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the, Manager, International Branch, ANM-116.

NOTE 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(g) The actions shall be done in accordance with Saab Service Bulletin 340-76-043, Revision 01, dated July 29, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

NOTE 5: The subject of this AD is addressed in Swedish airworthiness directive SAD No. 1-143, dated July 2, 1999.

(h) This amendment becomes effective on February 8, 2000.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**AIRBUS INDUSTRIE
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-09 AIRBUS INDUSTRIE: Amendment 39-11490. Docket 99-NM-327-AD. Issued December 23, 1999.

Applicability: Model A300 B4-203 series airplanes, certificated in any category, equipped with La Guardia main landing gears (MLG) and Messier Bugatti steel brakes.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent detachment of the brake bar from the MLG strut, which could result in failure of the MLG to extend, accomplish the following:

(a) Within 500 flight hours after the effective date of this AD, perform a detailed visual inspection to detect missing brake bar attachment bolts on the left and right MLG, in accordance with Airbus Service Bulletin A300-32-0430, dated January 29, 1999.

(1) If no attachment bolt is missing, prior to further flight, remove the attachment bolts, and perform a detailed visual inspection to detect damage, as specified by Figure 1 of the service bulletin. Accomplish the actions in accordance with the service bulletin.

(i) If no damage is detected, repeat the detailed visual inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 500 flight hours.

(ii) If any damage is detected, prior to further flight, replace the two attachment bolts with new bolts in accordance with the service bulletin. Repeat the detailed visual inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 500 flight hours.

(2) If any attachment bolt is missing, prior to further flight, replace the two attachment bolts with new bolts, in accordance with the service bulletin. Repeat the detailed visual inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 500 flight hours.

NOTE 2 For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

NOTE 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The actions shall be done in accordance with Airbus Service Bulletin A300-32-0430, dated January 29, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

NOTE 4: The subject of this AD is addressed in French airworthiness directive 1999-284-290(B), dated July 13, 1999.

(e) This amendment becomes effective on January 19, 2000.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**AIRBUS INDUSTRIE
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-10 AIRBUS INDUSTRIE: Amendment 39-11491. Docket 99-NM-222-AD. Issued December 23, 1999.

Applicability: Model A310 and A300-600 series airplanes, certificated in any category; except those on which Airbus Modifications 06267 and 07340 have been accomplished during production.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the fire warning from terminating prematurely, which could result in an unnoticed, uncontained engine/auxiliary power unit (APU) fire, accomplish the following:

Modifications

(a) Within 24 months after the effective date of this AD, accomplish the wiring modifications to the engine and APU fire detection system in the relay box 282VU and the electronics rack 90VU in accordance with Airbus Service Bulletin A310-26-2024, Revision 04, dated March 5, 1999 (for Model A310 series airplanes); or A300-26-6038, dated March 5, 1999, or Revision 1, dated September 8, 1999 (for Model A300-600 series airplanes); as applicable.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The modifications shall be done in accordance with Airbus Service Bulletin A310-26-2024, Revision 04, dated March 5, 1999; Airbus Service Bulletin A300-26-6038, dated March 5, 1999; or Airbus Service Bulletin A300-26-6038, Revision 1, dated September 8, 1999; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

NOTE 3: The subject of this AD is addressed in French airworthiness directive 1999-238-286(B), dated June 2, 1999.

(e) This amendment becomes effective on February 8, 2000.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**BRITISH AEROSPACE AIRBUS LIMITED
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-11 BRITISH AEROSPACE AIRBUS LIMITED (Formerly British Aerospace Commercial Aircraft Limited, British Aerospace Aircraft Group): Amendment 39-11492. Docket 99-NM-31-AD. Issued December 23, 1999.

Applicability: All Model BAC 1-11 200 and 400 series airplanes, certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To provide the flight crew with procedures in the event of uncommanded deployment of the thrust reverser and to prevent uncommanded deployment of the thrust reverser in flight or on the ground, which could result in reduced controllability of the airplane, accomplish the following:

(a) Within 30 days after the effective date of this AD, perform an inspection for proper rigging of the thrust reverser cable drums, in accordance with British Aerospace Alert Service Bulletin 76-A-PM6043, Issue No. 1, dated September 18, 1998. If any drum is found to be improperly rigged, prior to further flight, accomplish the adjustments specified in paragraph 3, "Adjustments," of the alert service bulletin.

(b) Prior to further flight after accomplishing the inspection required by paragraph (a) of this AD, perform an inspection for proper rigging of the thrust reverser selector valve detent, in accordance with Rolls-Royce Spey Service Bulletin Sp78-131, dated September 1998. If any discrepancy is found, prior to further flight, accomplish the adjustments specified in paragraph 3, "Adjustments," of the service bulletin.

(c) Within 30 days after the effective date of this AD, revise the Emergency and Abnormal Procedures Sections of the FAA-approved Airplane Flight Manual (AFM) by inserting, into the applicable sections of the AFM, British Aerospace Advance Amendment Bulletin No. 12 (for Model 400 series airplanes) or No. 16 (for Model 200 series airplanes), as applicable; both dated August 19, 1997.

(d) Within 12 months after the effective date of this AD, replace the thrust reverser control unit selector valve with a new or modified selector valve in accordance with British Aerospace Service Bulletin 78-PM6047, Revision 1, dated November 27, 1998.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector who may add comments and then send it to the Manager, International Branch, ANM-116.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(g) The actions shall be done in accordance with British Aerospace Alert Service Bulletin 76-A-PM6043, Issue No. 1, dated September 18, 1998; Rolls-Royce Spey Service Bulletin Sp78-131, dated September 1998; British Aerospace Service Bulletin 78-PM6047, Revision 1, dated November 27, 1998; British Aerospace Advance Amendment Bulletin No. 12, dated August 19, 1997; and British Aerospace Advance Amendment Bulletin No. 16, dated August 19, 1997. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace, Service Support, Airbus Limited, P.O. Box 77, Bristol BS99 7AR, England. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

NOTE 3: The subject of this AD is addressed in British airworthiness directives 002-09-98 and 005-11-98.

(h) This amendment becomes effective on February 8, 2000.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax(425) 227-1149.

**FOKKER SERVICE BV
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-13 FOKKER SERVICES B.V.: Amendment 39-11494. Docket 99-NM-236-AD. Issued December 28, 1999.

Applicability: All Model F27 Mark 050 series airplanes, certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loose attachment screws on the leading edges of the elevators, rudder, and ailerons due to vibration, which could result in interference of the leading edges with adjacent structure and consequent reduced controllability of the airplane; accomplish the following:

Repetitive Corrective Action

(a) Within 30 days after the effective date of this AD, use a torque wrench to tighten the screws for the attachment of the leading edges of the elevators in accordance with Fokker Service Bulletin SBF50-55-007, dated June 5, 1998. Repeat the tightening thereafter at intervals not to exceed 12 months.

(b) Within 24 months after the effective date of this AD, use a torque wrench to tighten the screws for the attachment of the leading edges of the rudder in accordance with Fokker Service Bulletin SBF50-55-009, Revision 1, dated July 23, 1999. Repeat the tightening thereafter at intervals not to exceed 4,000 flight hours or 24 months, whichever occurs first.

(c) Within 6 months after the effective date of this AD, use a torque wrench to tighten the screws for the attachment of the leading edges of the ailerons in accordance with Fokker Service Bulletin SBF50-57-020, Revision 1, dated July 23, 1999. Repeat the tightening thereafter at intervals not to exceed 12 months.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) The actions shall be done in accordance with the following Fokker service bulletins, which contain the specified effective pages:

Service Bulletin Referenced and Date	Page Number	Revision Level Shown on Page	Date Shown on Page
SBF50-55-007, June 5, 1998	1-5	Original	June 5, 1998
SBF50-55-009, Revision 1, July 23, 1999	1-4, 7, 5, 6	1, Original	July 23, 1999
SBF50-57-020, Revision 1, July 23, 1999	1-4, 6, 5, 7	1, Original	July 23, 1999

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, The Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

NOTE 3: The subject of this AD is addressed in Dutch airworthiness directive 1998-070/3, dated August 31, 1999.

(g) This amendment becomes effective on January 21, 2000.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**AIRBUS INDUSTRIE
AIRWORTHINESS DIRECTIVE
LARGE AIRCRAFT**

99-27-14 AIRBUS INDUSTRIE: Amendment 39-11495. Docket 99-NM-336-AD. Supersedes AD 99-01-05, Amendment 39-10980. Issued December 28, 1999.

Applicability: All Model A340-211, -212, -213, -311, -312, and -313 series airplanes; certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the inadvertent opening of a thrust reverser door in the event of failure of the primary and secondary locks of the thrust reverser, which could result in reduced controllability of the airplane, accomplish the following:

Operational Test

(a) Prior to the accumulation of 1,300 total flight hours, or within 500 flight hours after January 25, 1999 (the effective date of AD 99-01-15, amendment 39-10980), whichever occurs later, perform an operational test (inspection) to ensure proper operation of the actuator of the secondary locks of the thrust reversers, in accordance with Airbus Service Bulletin A340-78-4012, Revision 01, dated December 19, 1996, or Revision 05, dated July 6, 1999. Thereafter, repeat the operational test at intervals not to exceed 1,300 flight hours. After the effective date of this AD, only Revision 05 of the service bulletin shall be used.

NOTE 2: The Airbus service bulletin references ROHR Service Bulletin RA34078-47, Revision 1, dated November 30, 1996, as an additional source of service information for accomplishment of the operational test.

Corrective Action

(b) If any discrepancy is detected during any operational test (inspection) required by paragraph (a) of this AD, prior to further flight, replace the actuator of the secondary lock with a new or serviceable actuator, in accordance with ROHR Service Bulletin RA34078-47, Revision 1, dated November 30, 1996.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

NOTE 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The operational tests and replacement shall be done in accordance with Airbus Service Bulletin A340-78-4012, Revision 01, dated December 19, 1996; Airbus Service Bulletin A340-78-4012, Revision 05, dated July 6, 1999; and ROHR Service Bulletin RA3478-47, Revision 1, dated November 30, 1996, which contains the following list of effective pages:

Page number	Revision level shown on page	Date shown on page
1, 5, 6	1	November 30, 1996
2-4, 7	Original	September 16, 1996

(1) The incorporation by reference of Airbus Service Bulletin A340-78-4012, Revision 05, dated July 6, 1999, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Airbus Service Bulletin A340-78-4012, Revision 01, dated December 19, 1996; and ROHR Service Bulletin RA34078-47, Revision 1, dated November 30, 1996; was approved previously by the Director of the Federal Register as of January 25, 1999 (64 FR 1108, January 8, 1999).

(3) Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; and ROHR, Inc., 850 Lagoon Drive, Chula Vista, California 91912. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

NOTE 4: The subject of this AD is addressed in French airworthiness directive 1999-265-117(B), dated June 30, 1999.

(f) This amendment becomes effective on January 21, 2000.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax(425) 227-1149.

**GENERAL ELECTRIC COMPANY
AIRWORTHINESS DIRECTIVE
ENGINE
LARGE AIRCRAFT**

99-27-15 General Electric Company: Amendment 39-11496. Docket 99-NE-62-AD. Issues December 29, 1999.

Applicability: General Electric Company (GE) Models GE90-76B, -77B, -85B, -90B, and -92B turbofan engines, installed on but not limited to Boeing 777 series airplanes.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of thrust control due to corruption of the Ps3 and P3B signals to the full authority digital engine control (FADEC), which if it occurs in a critical phase of flight, could result in loss of aircraft control, accomplish the following:

Initial Inspection, Cleaning, Moisture Purging, and Blending

(a) Perform the following initial actions in accordance with the Accomplishment Instructions, Section (3) of GE Alert Service Bulletin (ASB) No. 73-A0060, dated December 23, 1999:

(1) Inspect, clean, moisture purge, and if necessary, blend any high metal, nicks, or burrs on fitting threads, on one engine installed on Boeing 777 series aircraft, within 10 cycles-in-service (CIS) after the effective date of this AD.

(2) Inspect, clean, moisture purge, and if necessary, blend any high metal, nicks, or burrs on fitting threads, on the other engine installed on the Boeing 777 series aircraft, within 20 CIS after the effective date of this AD.

Credit for Previous Inspections, Cleaning, and Moisture Purging

(b) Engines that have been inspected, cleaned, and moisture purged in accordance with GE90 All Reps Wire, JSB99-11-24-1, Revision 1, dated November 25, 1999, may count those inspections, cleaning, and moisture purging as accomplished and must be inspected, cleaned, moisture purged, and if necessary, have any high metal, nicks, or burrs on fitting threads blended, in accordance with the Accomplishment Instructions, Section (3) of GE ASB No. 73-A0060, dated December 23, 1999, and the following schedule:

(1) Engines that have accumulated 30 CIS or greater since previous inspection, cleaning, and moisture purging on the effective date of the AD must repeat the required procedures within 5 CIS after the effective date of this AD.

(2) Engines that have accumulated less than 30 CIS since previous inspection, cleaning, and moisture purging on the effective date of this AD must repeat the required procedures within 30 CIS since last inspection, or within 5 CIS after the effective date of this AD, whichever occurs later.

New and Replacement Engines

(c) For new and replacement engines, perform the initial inspection, cleaning, and moisture purging, and if necessary, blend any high metal, nicks, or burrs on fitting threads, prior to accumulating 30 CIS since entering service in accordance with the Accomplishment Instructions, Section (3) of GE ASB No. 73-A0060, dated December 23, 1999.

Repetitive Inspections

(d) Thereafter, inspect, clean, and moisture purge, and if necessary, blend any high metal, nicks, or burrs on fitting threads each engine within 30 CIS since last inspection, in accordance with the Accomplishment Instructions, Section (3) of GE ASB No. 73-A0060, dated December 23, 1999.

Idle Leak Check

(e) After accomplishing the required actions of this AD, and prior to entry into service, perform an idle leak check to confirm no Ps3 or P3B sense system faults in accordance with the Accomplishment Instructions, Section (3), paragraph (14), of GE ASB No. 73-A0060, dated December 23, 1999.

No Simultaneous Actions

(f) Do not perform the actions required by this AD concurrently on both engines installed on a Boeing 777 series aircraft

Alternative Methods of Compliance

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Ferry Flights

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(i) The actions required by this AD shall be done in accordance with GE ASB No. 73-A0060, dated December 23, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from General Electric Company via Lockheed Martin Technology Services, 10525 Chester Road, Suite C, Cincinnati, OH 45215; telephone 513-672-8400, fax 513-672-8422. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(j) This amendment becomes effective on January 11, 2000.

FOR FURTHER INFORMATION CONTACT:

John E. Golinski, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone 781-238-7135, fax 781-238-7199.

**CFE COMPANY
AIRWORTHINESS DIRECTIVE
ENGINE
LARGE AIRCRAFT**

99-27-16 CFE Company: Amendment 39-11497. Docket 99-NE-39-AD. Issued December 29, 1999.

Applicability: CFE Model CFE738-1-1B turbofan engines, serial numbers (S/Ns) 105267 through 105339, inclusive. These engines are installed on but not limited to Dassault-Breguet Falcon 2000 series aircraft.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent aft HPT cooling plate failure, which could result in an uncontained engine failure and damage to the airplane, accomplish the following:

Inspections and Follow-On Actions

(a) At the next engine shop visit after the effective date of this AD where the HPT assembly is sufficiently disassembled to afford access to the Stage 2 HPT aft cooling plate, but not later than 4500 part cycles-since-new (CSN), accomplish the following in accordance with CFE Alert Service Bulletin (ASB) No. CFE738-A72-8031, Revision 1, dated June 23, 1999, as follows:

(1) Inspect the stage 2 HPT aft cooling plate for nicks, dents, and scratches on surface D in accordance with the requirements of ASB No. CFE738-A72-8031, paragraph 2.B.(1).

(2) Repair those stage 2 HPT aft cooling plates with indentation less than 0.003 inch deep in accordance with ASB No. CFE738-A72-8031, paragraph 2.B.(1).

(3) Remove from service prior to further flight those stage 2 HPT aft cooling plates that have nicks, dents, and/or scratches that exceed the acceptance limits in accordance with ASB No. CFE738-A72-8031 paragraph 2.B.(1), and replace with serviceable parts.

(4) Inspect the stage 2 HPT rotor disk post aft mating surface for raised metal, and remove raised metal if present in accordance with ASB No. CFE738-A72-8031, paragraph 2.B.(2).

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Ferry Flights

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the inspection requirements of this AD can be accomplished.

Incorporation by Reference

(d) The actions required by this AD shall be done in accordance with the following CFE ASB:

Document No.	Revision	Pages	Date
CFE738-A72-8031	1	1	June 23, 1999
	Original	2-5	May 17, 1999
Total pages: 5.			

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from CFE Company, Data Distribution, MS 64-03/2101-201, P.O. , PO Box 29003 Phoenix, AZ 85038-9003; telephone (602) 365-2493, fax (602) 365-5577. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(e) This amendment becomes effective on February 10, 2000.

FOR FURTHER INFORMATION CONTACT:

Keith Mead, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7744, fax (781) 238-7199.

**BOMBARDIER
AIRWORTHINESS DIRECTIVE
EMERGENCY
LARGE AIRCRAFT**

2000-01-51 BOMBARDIER: Docket No. 2000-NM-05-AD.

Applicability: CL-604 variant of Canadair Model CL-600-2B16 series airplanes, modified in accordance with Supplemental Type Certificates SA8060NM-D, SA8072NM-D, or SA8086NM-D; certificated in any category.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been otherwise modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a fuel fire due to electrical sparks contacting the maintenance light housing of the fuel service panel, accomplish the following:

(a) Within 48 hours after receipt of this AD, perform the actions specified in paragraphs (a)(1), (a)(2), (a)(3), (a)(4), (a)(5), (a)(6), and (a)(7) of this AD.

(1) Open and lock-out the circuit breaker CB5-B8 located in the aft equipment bay at STA.645L on the JB5 panel.

(2) Open the refuel/defuel door located on the right side of the fuselage at the wing root . Remove the maintenance light receptacle by removing the four screws holding the receptacle to the fairing.

(3) Pull the light receptacle away from the fairing revealing the two wire leads attached to the receptacle.

(4) Disconnect the wires by removing the two screws that attach the wire leads to the light receptacle.

(5) Cap and stow the wires to prevent contact with metal objects within the fairing.

(6) Re-install the light receptacle in the fairing.

(7) Close circuit breaker CB5-B8.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) AD 2000-01-51, issued on January 7, 2000, becomes effective upon receipt.

FOR MORE INFORMATION CONTACT:

Abby Malmir, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5351; fax (562) 627-5210.

Issued in Renton, Washington, on January 7, 2000.

Donald L. Riggan, Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.